

With 200A of cleaning power, the Fury200 is the king of the Cougartron weld-cleaning range. Designed for the toughest and most demanding industrial applications, the Fury200 is unbeatable in raw power and performance. Clean heavy gauge TIG and MIG weld seams with ease with this high-performance machine.

Key features:

- Fast and effective cleaning power for all kinds of TIG and MIG weld seams.
- Robust design with tough case.
- Highly mobile with large-diameter rubber wheels.
- Easy to transport with collapsible steel handle.
- 20' Work and ground cables are standard.
- 1, 2 and 3-brush adaptors available.
- Highly adjustable – both amp and volt settings can be adjusted for optimal cleaning & polishing.



Technical data

Power supply	230 V AC, 50/60Hz, 10A
Weld-cleaning: Amp range	20-200A, 20A increments
Weld-cleaning: Voltage range	10-16 V AC
Polishing: Amp range	20-200A, 20A increments
Polishing: Voltage range	10-12 V DC
Marking: Amp range	2-10A, 2A increments
Marking: Voltage range	12 V AC
Duty cycle	100%
Detachable handle	Yes
Input cable length	12'
Output cable length	20'
Output cable Size	2 AWG
Brush holder options	1,2,3 & 4
Fluid feed compatible	No
Size (machine only)	15x13x25" (machine unit), 15x13x46" (unit with handle extended)
Enclosure protection	IP51
Certification	CE, UL, CSA



Set buying information

Description	Weight	Part nr.
Fury200 Weld-cleaner - Basic Set	133 lbs	WELC1110
Fury200 Weld-cleaner - Starter Set A	135 lbs	WELC1111
Fury200 Weld-cleaner - Starter Set B	142 lbs	WELC1112
Fury200 Weld-cleaner - Starter Set C	147 lbs	WELC1113

Set contents

Part nr.	Description	Basic Set	Starter Set A	Starter Set B	Starter Set C
n/a	Fury200 weld-cleaner (machine only)	x	x	x	x
WELC2064	Transport case - Large	x	x	x	x
WELC5006	Foam insert for large transport case (WELC2064)	x	x	x	x
WELC2577	Cable with handle 20 ft, 200A (dinse)	x	x	x	x
WELC2578	Cable with ground clamp 20 ft, 200A (dinse)	x	x	x	x
WELC2911	Protective Cover Large - 1 pc	x	x	x	x
WELC2574	Drip Tray		x	x	x
WELC3177	CGT-550 Weld Cleaning & Polishing Fluid - 1 Gal		x	x	x
WELC3186	CGT-N5 HyPerformance Neutralizing Fluid - 1 Gal		x	x	x
WELC2470	Wand/twist shroud set (for 1x M8 brush)		x	x	x
WELC2448	Wand/twist shroud set (for 2x M8 brush)		x	x	x
WELC2313	Wand/twist shroud set (for 3x M8 brush)		x	x	x
WELC3149	Fury brush (M8, 80A) - 10 pack		x	x	x
WELC2201	Spray bottle with sprayer 1 pt (empty)		x	x	x
WELC2005	Acid pot 1 pt with lid		x	x	x
WELC2630	Microfibre cloth - 27 x 27 inch (orange)		x	x	x
WELC2867	Cougartron acid resistant gloves - 1 pair		x	x	x
WELC2868	Cougartron safety glasses			x	x
WELC4045	Marking set for weld-cleaning machine (Standard)*			x	
STEN1029	Stencil voucher - max size 6x4"			x	x
WELC4956	Marking set for weld-cleaning machine (Advanced)*				x

Additional equipment and spares:

Part nr.	Item
WELC2889	Mobile workstation
WELC2579	Extension cable, orange 20 ft, 200A (dinse)

* Refer to page 76 for the Marking Sets.

WELD CLEANING

WELD CLEANING