The Cougartron Fury series is designed for the toughest and most demanding industrial applications. With 100A of highly-adjustable cleaning & polishing power, the Fury100 will take all that you can throw at it, and come back asking for more!

## **Key features:**

- Fast and effective cleaning power for all kinds of TIG and MIG weld seams.
- Robust design with tough case.
- Highly mobile with large-diameter rubber wheels.
- Easy to transport with collapsible steel handle.
- 6m Work lead and earth lead as standard.
- 1, 2 and 3-brush adaptors available.
- Highly adjustable both amp and volt settings can be adjusted for optimal cleaning & polishing.



Technical data		
Power supply: 110/230V version	N/A	
Power supply: 110V version	110 V AC, 50/60Hz, 15A	
Power supply: 230V version	240 V AC, 50/60Hz, 10A	
Weld-cleaning: Amp range	10-100A, 10A increments	
Weld-cleaning: Voltage range	10-16 V AC	
Polishing: Amp range	10-100A, 10A increments	
Polishing: Voltage range	10-12 V DC	
Marking: Amp range	2-10A, 2A increments	
Marking: Voltage range	12 V AC	
Duty cycle	100%	
Detachable handle	Yes	
Input cable length	4m	
Output cable length	6m	
Output cable Size	35mm²	
Brush holder options	1, 2	
Fluid feed compatible	Yes (Max 80A)	
Size (machine only)	W 39cm, H 64cm (machine unit) / 116,5cm (unit with han- dle extended), D 33cm	
Enclosure protection	IP53	
Certification	CE	



**Set buying information** 

Description	Weight	110V	230V
Fury 100 Weld-cleaner - Basic Set	50,0 kg	WELC1104	WELC1100
Fury100 Weld-cleaner - Starter Set A	51,0 kg	WELC1105	WELC1101
Fury100 Weld-cleaner - Starter Set B	54,3 kg	WELC1106	WELC1102
Fury100 Weld-cleaner - Starter Set C	55,5 kg	WELC1107	WELC1103

## **Set contents**

Part nr.	Description	Basic Set	Starter Set A	Starter Set B	Starter Set C
n/a	Fury100 weld-cleaner (machine only)	Х	Х	Х	Х
WELC2064	Transport case - Large	Х	Х	Х	Х
WELC5006	Foam insert for large transport case (WELC2064)	Х	Х	Х	Х
WELC2577	Lead with handle 6M, 200A (dinse)	Х	Х	Х	Х
WELC2578	Lead with earth clamp 6M, 200A (dinse)	Х	Х	Х	Х
WELC2574	Drip Tray	Х	Х	Х	Х
WELC3048	CGT-550 Weld Cleaning & Polishing Fluid - 5L		Х	Х	Х
WELC3158	CGT-N5 HyPerformance Neutralising Fluid - 5L		Х	Х	Х
WELC2470	Wand/twist shroud set (for 1x M8 brush)		Х	Х	Х
WELC2448	Wand/twist shroud set (for 2x M8 brush)		Х	Х	Х
WELC3149	Fury brush (M8, 80A) - 10 pack		Х	Х	Х
WELC2150	Cougartron USB storage device		Х	Х	Х
WELC2201	Spray bottle with sprayer 0.5L (empty)		Х	Х	Х
WELC2005	Acid pot 500ml with lid		Х	Х	Х
WELC2630	Microfibre cloth - 70x70cm (orange)		Х	Х	Х
WELC2867	Cougartron acid resistant gloves - 1 pair		Х	Х	Х
WELC2868	Cougartron safety glasses			Х	Х
WELC4045	Marking set for weld-cleaning machine (Standard)***			Х	
STEN1029	Stencil voucher - max size 150x100mm			Х	Х
WELC4956	Marking set for weld-cleaning machine (Advanced)***				Х

## Extra equipment

Extra equipment			
Part nr.	Description	Catalogue page	
WELC1059	FL10 Fluid Feed system*	30	
WELC2570	Mobile equipment stand**	34	
WELC2826	Mobile workstation	35	

<sup>\*</sup> Max cleaning power 80A with the FL10 fluid feed system

<sup>\*\*</sup> Mobile equipment stand can be used for FL10 and consumables only

<sup>\*\*\*</sup> Refer to page 64 for the Marking Sets.