Fury100XF

Our FURY100 weld cleaner just received an upgrade – now featuring a fully integrated fluid feed system for faster and more convenient weld cleaning. The FURY100XF is available in standard 230V and 110V inputs. The 110V version enhances portability and usability in locations where stronger current inputs are unavailable. Despite the lower input voltage, the machine effectively cleans both light and dark MIG welds, making it a unique solution in the market.

Key features:

- Fully integrated fluid feed.
- TIG weld cleaning with a 100% duty cycle.
- MIG weld cleaning (up to 10mm thickness).
- Marking and Etching compatible with the Cougartron Basic Etching Set
- Easy to transport with collapsible steel handle.
- 6m work lead and earth lead as standard.
- 1, 2 and 3-brush adaptors available.
- Highly adjustable both amp and volt settings can be adjusted for optimal cleaning & polishing.



| Technical data | |
|--------------------------------|---|
| Power supply: 110/230V version | N/A |
| Power supply: 110V version | 110 V AC, 50/60Hz, 32A |
| Power supply: 230V version | 240 V AC, 50/60Hz, 16A |
| Weld-cleaning: Amp range | 20-100A, 20A increments |
| Weld-cleaning: Voltage range | 10-16 V AC |
| Polishing: Amp range | 20-100A, 20A increments |
| Polishing: Voltage range | 10-12 V DC |
| Marking: Amp range | 2-10A, 2A increments |
| Marking: Voltage range | 12 V AC |
| Duty cycle | 100% |
| Detachable handle | Yes |
| Input cable length | 4m |
| Output cable length | бт |
| Output cable Size | 35mm ² |
| Brush holder options | 1, 2, 3 |
| Fluid feed compatible | Fully integrated |
| Size (machine only) | W 39cm, H 64cm (machine unit) / 116,5cm (unit with handle extended), D 33cm |
| Enclosure protection | IP53 |
| Certification | CE |

Set buying information

| Set buying internation | | | | | | | |
|--|---------|----------|----------|--|--|--|--|
| Description | Weight | 110V | 230V | | | | |
| Fury100XF Weld-cleaner - Basic Set | 60,0 kg | WELC1134 | WELC1130 | | | | |
| Fury100XF Weld-cleaner - Starter Set A | 61,0 kg | WELC1135 | WELC1131 | | | | |
| Fury100XF Weld-cleaner - Starter Set B | 64,3 kg | WELC1136 | WELC1132 | | | | |
| Fury100XF Weld-cleaner - Starter Set C | 66,5 kg | WELC1137 | WELC1133 | | | | |

Set contents

| Part nr. | Description | Basic Set | Starter Set A | Starter Set B | Starter Set C |
|----------|---|--------------|------------------|------------------|------------------|
| n/a | Fury100XF weld-cleaner (machine only) | х | х | х | х |
| WELC2064 | Transport case - Large | х | х | х | х |
| WELC5006 | Foam insert for large transport case (WELC2064) | х | х | х | х |
| WELC2577 | Lead with handle 6M, 200A (dinse) | Х | х | х | х |
| WELC2578 | Lead with earth clamp 6M, 200A (dinse) | х | х | х | х |
| WELC2574 | Drip Tray | | х | х | х |
| WELC3048 | CGT-550 Weld Cleaning & Polishing Fluid - 5L | | х | х | х |
| WELC3158 | CGT-N5 HyPerformance Neutralising Fluid - 5L | | х | х | х |
| WELC2891 | Wand/twist shroud set for fluid feed (1x M8 brush) | | х | х | х |
| WELC2892 | Wand/twist shroud set for fluid feed (2x M8 brush) | | х | х | х |
| WELC3149 | Fury brush (M8, 80A) - 10 pack | | х | х | х |
| WELC2150 | Cougartron USB storage device | | х | х | х |
| WELC2201 | Spray bottle with sprayer 0.5L (empty) | | х | х | х |
| WELC2005 | Acid pot 500ml with lid | | x | х | х |
| WELC2630 | Microfibre cloth - 70x70cm (orange) | | х | х | х |
| WELC2867 | Cougartron acid resistant gloves - 1 pair | | х | х | х |
| WELC2868 | Cougartron safety glasses | | | х | х |
| WELC4045 | Marking set for weld-cleaning machine (Standard)*** | | | х | |
| STEN1029 | Stencil voucher - max size 150x100mm | | | х | х |
| WELC4956 | Marking set for weld-cleaning machine (Advanced)*** | | | | х |

Extra equipment

| Part nr. | Description | Catalogue page |
|----------|--------------------------|----------------|
| WELC2570 | Mobile equipment stand** | 38 |
| WELC2826 | Mobile workstation | 39 |

* Max cleaning power 80A with the FL10 fluid feed system

** Mobile equipment stand can be used for FL10 and consumables only *** Refer to page 64 for the Marking Sets.

erer to page 64 for the Marking Sets.