

With 200A of cleaning power, the Fury200 is the king of the Cougartron weld-cleaning range. Designed for the toughest and most demanding industrial applications, the Fury200 is unbeatable in raw power and performance. Clean heavy gauge TIG and MIG weld seams with ease with this high-performance machine.

Key features:

- Fast and effective cleaning power for all kinds of TIG and MIG weld seams.
- Robust design with tough case.
- Highly mobile with large-diameter rubber wheels.
- Easy to transport with collapsible steel handle.
- 6m work lead and earth lead as standard.
- 1, 2 and 3-brush adaptors available.
- Highly adjustable – both amp and volt settings can be adjusted for optimal cleaning & polishing.



Technical data

Power supply: 110/230V version	N/A
Power supply: 110V version	110 V AC, 50/60Hz, 32A
Power supply: 230V version	240 V AC, 50/60Hz, 16A
Weld-cleaning: Amp range	20-200A, 20A increments
Weld-cleaning: Voltage range	10-16 V AC
Polishing: Amp range	20-200A, 20A increments
Polishing: Voltage range	10-12 V DC
Marking: Amp range	2-10A, 2A increments
Marking: Voltage range	12 V AC
Duty cycle	100%
Detachable handle	Yes
Input cable length	4m
Output cable length	6m
Output cable Size	35mm ²
Brush holder options	1, 2, 3
Fluid feed compatible	No
Size (machine only)	W 39cm, H 64cm (machine unit) / 116,5cm (unit with handle extended), D 33cm
Enclosure protection	IP51
Certification	CE



Set buying information

Description	Weight	110V	230V
Fury200 Weld-cleaner - Basic Set	60,0 kg	WELC1114	WELC1110
Fury200 Weld-cleaner - Starter Set A	61,0 kg	WELC1115	WELC1111
Fury200 Weld-cleaner - Starter Set B	64,3 kg	WELC1116	WELC1112
Fury200 Weld-cleaner - Starter Set C	66,5 kg	WELC1117	WELC1113

Set contents

Part nr.	Description	Basic Set	Starter Set A	Starter Set B	Starter Set C
n/a	Fury200 weld-cleaner (machine only)	x	x	x	x
WELC2064	Transport case - Large	x	x	x	x
WELC5006	Foam insert for large transport case (WELC2064)	x	x	x	x
WELC2577	Lead with handle 6M, 200A (dinse)	x	x	x	x
WELC2578	Lead with earth clamp 6M, 200A (dinse)	x	x	x	x
	Protective Cover Big -1Pc	x	x	x	x
WELC2574	Drip Tray		x	x	x
WELC3048	CGT-550 Weld Cleaning & Polishing Fluid - 5L		x	x	x
WELC3158	CGT-N5 HyPerformance Neutralising Fluid - 5L		x	x	x
WELC2470	Wand/twist shroud set (for 1x M8 brush)		x	x	x
WELC2448	Wand/twist shroud set (for 2x M8 brush)		x	x	x
WELC2313	Wand/twist shroud set (for 3x M8 brush)		x	x	x
WELC3149	Fury brush (M8, 80A) - 10 pack		x	x	x
WELC2201	Spray bottle with sprayer 0.5L (empty)		x	x	x
WELC2005	Acid pot 500ml with lid		x	x	x
WELC2630	Microfibre cloth - 70x70cm (orange)		x	x	x
WELC2867	Cougartron acid resistant gloves - 1 pair		x	x	x
WELC2868	Cougartron safety glasses			x	x
WELC4045	Marking set for weld-cleaning machine (Standard)*			x	
STEN1029	Stencil voucher - max size 150x100mm			x	x
WELC4956	Marking set for weld-cleaning machine (Advanced)*				x

Additional equipment and spares:

Part nr.	Item
WELC2889	Mobile workstation
WELC2579	Extension cable, orange 20ft, 200A (dinse)

* Refer to page 76 for the Marking Sets.

WELD CLEANING

WELD CLEANING