

The Fury200XF, equipped with an integrated fluid feed, stands as one of the top choices among our weld cleaning machines, making your cleaning tasks faster and more effective. It's designed to handle tough industrial jobs with unmatched power and performance. Easily clean heavily oxidized TIG/MIG welds and achieve top-notch results by exploring the full potential of this powerful weld cleaner. Control the amount of fluid delivered to your brush using the practical display screen.

Key features:

- Fully integrated fluid feed.
- Fast and effective cleaning power for all kinds of TIG and MIG weld seams.
- Robust design with tough case.
- Highly mobile with large-diameter rubber wheels.
- Easy to transport with collapsible steel handle.
- 20' Work and ground cables are standard.
- 1, 2, and 3-brush adaptors available, as well as our brand-new mop attachment.
- Highly adjustable – both amp and volt settings can be adjusted for optimal cleaning & polishing.



Technical data

Power supply	230 V AC, 50/60Hz, 10A
Weld-cleaning: Amp range	20-200A, 20A increments
Weld-cleaning: Voltage range	10-16 V AC
Polishing: Amp range	20-200A, 20A increments
Polishing: Voltage range	10-12 V DC
Marking: Amp range	2-10A, 2A increments
Marking: Voltage range	12 V AC
Duty cycle	100%
Detachable handle	Yes
Input cable length	12'
Output cable length	20'
Output cable Size	2 AWG
Brush holder options	1,2,3 & Mop
Fluid feed compatible	Fully integrated
Size (machine only)	15x13x25" (machine unit), 15x13x46" (unit with handle extended)
Enclosure protection	IP51
Certification	CE, UL, CSA



Set buying information

Description	Weight	Part nr.
Fury200XF Weld-cleaner - Basic Set	133 lbs	WELC1120
Fury200XF Weld-cleaner - Starter Set A	135 lbs	WELC1121
Fury200XF Weld-cleaner - Starter Set B	142 lbs	WELC1122
Fury200XF Weld-cleaner - Starter Set C	147 lbs	WELC1123

Set contents

Part nr.	Description	Basic Set	Starter Set A	Starter Set B	Starter Set C
n/a	Fury200XF weld-cleaner (machine only)	x	x	x	x
WELC2064	Transport case - Large	x	x	x	x
WELC5006	Foam insert for large transport case (WELC2064)	x	x	x	x
WELC2878	Cable with handle 20ft, 200A (dinse w. fluid feed)	x	x	x	x
WELC2578	Cable with ground clamp 20ft, 200A (dinse)	x	x	x	x
WELC2911	Protective Cover Large -1pc	x	x	x	x
WELC2574	Drip Tray		x	x	x
WELC3177	CGT-550 Weld Cleaning & Polishing Fluid - 1 Gal		x	x	x
WELC3186	CGT-N5 HyPerformance Neutralizing Fluid - 1 Gal		x	x	x
WELC2891	Wand/twist shroud set for fluid feed (1x M8 brush)		x	x	x
WELC2892	Wand/twist shroud set for fluid feed (2x M8 brush)		x	x	x
WELC2926	Wand/twist shroud (3x M8 brush, fl/f, straight)		x	x	x
WELC3149	Fury brush (M8, 80A) - 10 pack		x	x	x
WELC2201	Spray bottle with sprayer 1 pt (empty)		x	x	x
WELC2005	Acid pot 1 pt with lid		x	x	x
WELC2630	Microfibre cloth - 27 x 27 inch (orange)		x	x	x
WELC2867	Cougartron acid resistant gloves - 1 pair		x	x	x
WELC2868	Cougartron safety glasses			x	x
WELC4045	Marking set for weld-cleaning machine (Standard)*			x	
WELC5037	Cleaning fluid bottle w. drilled cap - 1 Gal		x	x	x
WELC2577	20 ft Power Cable with Handle, 200A, Non-Fluid Feed			x	x
STEN1029	Stencil voucher - max size 6x4"			x	x
WELC4956	Marking set for weld-cleaning machine (Advanced)*				x

Additional equipment and spares:

Part nr.	Item
WELC2889	Mobile workstation
WELC2579	Extension cable, orange 20ft, 200A (dinse)
WELC2580	Extension cable, black 20ft, 200A (dinse)

* Refer to page 76 for the Marking Sets.

WELD CLEANING

WELD CLEANING